

Reference #: PB13-002

Date: 17<sup>h</sup> June 2013

**Affected Products:** 2151BAUS – Conventional Photoelectric Detector

SYSTEM SENSOR has identified a technical issue with model 2151BAUS conventional photoelectric detectors manufactured in December 2012 that has resulted in the failure of the detector's optical sensor in a small percentage of devices. A failure of the optical sensor will be indicated at the device as a chamber / maintenance fault, which is presented to the user by the LEDs on the detector no longer flashing.

It is recommended that as part of the regular scheduled maintenance procedures of a fire detection system, particular attention should be taken to ensure that all 2151BAUS detectors are functioning normally and any faulty devices returned to Notifier for replacement.

2151BAUS detectors with serial numbers 2125734478 – 2125740237 are the only units affected by this issue.

Contact your systems consultant for more information.

Sincerely,



James Edwards  
Product Manager