

Release AFP-3030/NCA-2 Service Pack V24.10

NOTIFIER is pleased to announce the release of Service Pack V24_10 for AFP-3030 and NCA-2. The Service Pack includes the following firmware:

- AFP-3030 CPU v24.10
- NCA-2 CPU v24.10
- ELCM-320 v12.006.B05
- NCM-WCPA v3.60 B06

This Service Pack provides the following changes;

New features:

- Added Alarm Delay Facility, configurable from 30 to 300 seconds.

Resolved issues:

- Corrected issue whereby the PSI External input fault was not reporting when the panel is rebooted.
- Corrected issue whereby the ACM-PSI point 2 charger inhibited was not updated.

Compatibility:

- This software is compatible with CPU2-3030PCD Rev D hardware and above. The model number of this hardware is CPU2-3030ND-AUS.
- The Service Pack includes LCM and NCM and should be used to upgrade these modules to required versions.
- Notifier Australian Verifier Tools V9.20 or higher is needed to program Alarm Delay Facility via VFT.

Installation Steps:

- Notifier Australian Verifier Tools V9.10 or higher is needed to download the AFP3030 firmware to the panel.
- Do not downgrade panel from V24 or above to V23. Different files are needed to perform this downgrading. Please check with Engineering if needed.

Please contact your NOTIFIER technical support for any technical questions.