

## Release AFP-3030/NCA-2 Service Pack V24.11

NOTIFIER is pleased to announce the release of Service Pack V24\_11 for AFP-3030 and NCA-2. The Service Pack includes the following firmware:

- **AFP-3030 CPU v24.11 B01**
- **NCA-2 CPU v24.11 B01**
- **ELCM-320 v12.006 B05**
- **NCM-WCPA v3.60 B06**

**This Service Pack provides the following changes;**

*Resolved issues:*

- Corrected issue whereby CPU Notification Appliance Circuits (NACs) would momentarily toggle during a system reset. This issue would only occur if the NAC was activated during an alarm event.

**Compatibility:**

- This software is compatible with CPU2-3030PCD Rev D hardware and above. The model number of this hardware is CPU2-3030ND-AUS.
- The Service Pack includes LCM and NCM and should be used to upgrade these modules to required versions.
- Notifier Australian Verifier Tools V9.20 or higher is needed to program Alarm Delay Facility via VFT.

**Installation Steps:**

- Notifier Australian Verifier Tools V9.10 or higher is needed to download the AFP3030 firmware to the panel.
- Do not downgrade panel from V24.xx or above to V23.xx Different files are needed to perform this downgrading. Please check with product support if needed.

Please contact your NOTIFIER product support for any technical questions.