

## **Version 4.22 Firmware - Embedded Gateways (Board Type: PCA)**

NOTIFIER has identified a non-safety related issue with Version 4.22 Firmware for embedded gateways with Board Type: PCA for the following part numbers (NFN-GW-AU-EM-3, BACNET-GW-3) which can cause the gateways to lose communication with the respective client after 7 days from commissioning. To correct this issue, we recommend all affected gateways running version 4.22 be upgraded to version 4.23 at the next service interval.

The latest firmware is available for download from [www.notifier.com.au](http://www.notifier.com.au)

Please contact your NOTIFIER product support for any technical questions.